**SLANPRO** 

123 Manual, LP-FIFSCXX In-Fusion® Field Fusion-splicing connector SC Assembly Instructions

LPFIFSCXX\_M123\_ENB01W






123 Manual

LP-FIFSCXX In-Fusion® Field Fusion-splicing connector SC

**Assembly Instructions** 


## Assembling procedure:



1. Pass the cable through the boot and the boot cap




2. Strip Drop cable with a stripper



3. Clean the stripped cable with alcohol soaked tissue




4. Cleave it with a cleaver



5. Place the LP-FIFSCXX onto LPT-FIFCM1000




6. Splice





**7.** Fold wings together for spliced-point protection

8. Assemble the boot and the cap



9. Assemble the Housing